


# WWW.1999.GR


## **2003-2005 VOLVO XC90**

**1** Disconnect the negative battery terminal to prevent an accidental short circuit.

**2** Move the shifter to the rearmost position, unsnap the shifter trim and move it to one side. (Figure A)



**3** Remove two screws from bottom of the radio/ climate control cluster. **CAUTION:** Do not remove connectors before turning the ignition off. (Figure B)



**4** With radio and climate controls out, remove four screws holding the radio to the bracket, release the clips and remove the radio. (Figure C)

