

99-9223 Volvo S60 / V70

- 1** Disconnect the negative battery terminal to prevent an accidental short circuit.

- 2** Unsnap gearshift trim bezel and slide back.

See figure A

- 3** Remove (2) T-25 Torx from climate control assembly, proceed to unsnap assembly from radio bottom.

See figure B

- 4** Remove (2) T-25 Torx from radio bottom in climate control cavity to remove radio.

See figure C



● DASH DISASSEMBLY